AA-1073 Before 1876

Fernglen Manor
Glen Burnie
Private

Fernglen Manor is important architecturally as being an example of a 3rd quarter 19th century, Gothic Revival style, 1-house. This house is representative of dwellings constructed by relatively affluent farm families, both locally and in other established sections of the country, from the second half of the 19th century into the first quarter of the 20th century.

The house was probably built by Charles Pumphrey around 1876 on a tract of land known as Pumphreys Search, Fernglen Manor's significance is enhanced because of its association with truck farming, once the dominant from of economic activity of this region in Anne Arundel County.

AA-1073 Fernglen Manor

MARYLAND COMPREHENSIVE STATE HISTORIC PRESERVATION PLAN DATA

Geographic Organization: Western Shore

Chronological/Development Period(s): Industrial/Urban Dominance (1870-1930)

Prehistoric/Historic Period Theme(s): Architecture

Resource Type:

Category Type: Building Historic Environment: Rural

Historic Function(s) and Use(s): dwelling

Known Design Source: NONE

Maryland Historical Trust State Historic Sites Inventory Form

Survey No. AA-1073

Magi No.

DOE ____yes ____no

1. Name	(indicate professed name)			
i. Name	(indicate preferred name)			
historic	Femglen Manor	-		
and/or common				
2. Locati	on			
street & number	13 Hopkins Street		not	for publication
city, town	Glen Bumie	vicinity of	congressional district	
state	Maryland	county	Anne Arundel	
3. Classi	fication			
Category district x building(s) structure site object	Ownership public x private both Public Acquisition in process being considered not applicable	x occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted	Present Useagriculturecommercialeducationalentertainmentgovernmentindustrialmilitary	museum park x private residence religious scientific transportation other:
4. Owner	of Property	(give names and mailing ad	ddresses of <u>all</u> owners)	
name	Brenda Poist	-		
street & number	13 Hopkins Street		telephone no.: (41	0) 766-6659
city, town	Glen Bumie	state and zip code:	Maryland	
5. Location	on of Legal Des	cription		
courthouse, registr	y of deeds, etc. Anne An	undel County Courthouse	libe	г 5659
street & number			folio	453
city, town	Annapolis		state Marylan	d
6. Repres	sentation in Exi	sting Historical	Surveys	
title				
date		federal	state cou	n local
ository for surv	ey records			
city, town		·····	state	

Condition excellent good	deteriorated	Check one x unaltered altered	Check onexoriginal sitemoved date of move	
xfair	unexposed			

Survey No. AA-1073

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

Located at the end of a dirt drive way and surrounded by mature hardwood trees, Femglen Manor, a late-19th century dwelling, is situated in a post-World War II tract development. It is a vemacular gothic-revival style building, but architectural suggest the possible incorporation of an older building.

Its present form is a two-and-a-half story, three-bay, centered cross-gable frame house. It faces south and consists of a center-hall plan, single-pile, front block, with a two-and-a-half ell projecting from the building's anterior end. Walls are primarily covered with German siding, with plain clapboards sheathing the ell. The front I-house section rests on a brick foundation, and is situated slightly above grade level. The rear ell sits on a fieldstone foundation atop a deep basement accessed via exterior bulkhead. Visible from the basement are the round logs which serve as floor joists for the ell. The sills and joists under the front block are sawn. (Only a small portion was exposed and saw marks were not discernible.)

A one-story, shed-roofed bathroom and porch addition is located on the east side, at the intersection of the front block and rear ell. Its walls are covered in the same manner as the ell.

Two broad, interior-stack fireplace chimneys are present on either side of the front block, while a narrow, interior stove chimney pierces the roof of the ell. Parging obscures the brickwork of the former two, but reportedly recent repairs revealed significant variations between them.

The front facade is dominated by an open, shed-roofed porch, which is supported by four, turned posts, embellished near the roofline with jig-sawn quatrefoil motives. A two-story porch projects from the west side of the ell, extending slightly beyond the longitudinal axis of the front block. Each level is supported by three square posts. The top level retains its flat jig-sawn balustrade.

On the primary facade, fenestration consists of three pairs of two-over-two double-hung sash windows. This window type, though arranged singly elsewhere, predominates throughout the building. The ell also displays six-over-six, and two-over-two windows. The centrally located front entrance features a tripartite transom and flanking sidelights. The wooden door contains four panels, accented with raised molding. The two located in the door's upper half are finished have arched tops, and are approximately one-fourth longer than the pair in the door's lower section.

The building's interior retains much of its original finish, including a mantle with spindlework, a marble hearth, and fancy turned newel and balustrade. The second floor and finished attic level, display a significantly lower level of finish. Door and window surrounds are less elaborate and the floor boards, which are regular and mostly quartersawn on the first floor, are randomly sized+A66 and tangentially cut on the upper level.

The finish treatment of the ell differs from the main house. The detail of the woodwork and trim is obscured by multiple layers of paint, but appear older (and certainly have more paint layers) than the main section. Significant interior features included a pair of built-in cupboards, located on the west side of the north wall, left of a nineteenth-century wood stove. On the same wall, on the stove's right side, i oor that provides access to a extremely steep winder stair thatleads to the ell's upper level. The presence of this door is de-emphasized through the application of the same beaded board used to cover the cupboard and most of the wall.

(see continuation sheet)

Description

8.	Signif	icance				·	-			Survey No	. AA-1073
Period Areas of Signification prehistoric archeology-archeology-archeology-agriculture 1500-1599 x agriculture 1600-1699 x architecture x 1800-1899 commerce 1900- communication		conservation			law literat milita music	ure ry	chitecture	religion science sculpture social/ humanitanar theater transportatio other (specif			
Spec	ific dates		Bu	ilder/	Architect	•					
Chec	Applica	able Criteria: and/or ble Exception: f Significance:	xA Anational	B B	x_C C state		D D Local	E _	F	G	
Charle The Ir in	es Pumphrey nouse sits on third quarter ral Direct Tax bying a wood nother outho phrey family, in his minon	tween 1840-1880. y (b. before 1842 - a part of a tract of r of the 18th centur x records for that y en house measurin use measuring 36 with sections parc ty. 1842 Chancery homas (see AA-77	d. 1897), a wearly and occupied ear record Ebeng 28' x 18', as ' x 20'. (1) Afte eled off to varidy Court records	althy A Pump I by 1 neeze well a r Eber bus far	Anne Arund ohreys Sea 798 (1). or Pumphre os two outhoneezer's de mily memb oe related t	y owning ouses reath, the ers. Control of the a	inty farr umprhe ng 212 neasun e land r harles l	mer and to ys Search acres of I ng 20' x remained Pumphre	Pumphr 16', in the y inherit	atented eys Search a	nd
well a memi a truc Baltin	is portions of bers lived in ok farmer, spo nore. Invent	possession of "the several other trac close proximity (3) ecializing in the pro ones taken at his c antaloupes and en	ts. Atlases indi . Like many me oduction of fruit leath indicate th	cate hember s and nat, at	nis siblings, s of his fan vegetable: least late i	as we nily, Ch s for co	ll as oth narles b onsume	er family ecame r markets	; s in	ng	
produ a wisl	ce to market n to capitalize	ick farming was ind . Perhaps a guaral e on this mutual ne interest in a Patap	nteed method o eed of fellow far	f tran: mers,	sportation a motivated	across Charle	the Pat				
		emglen Manor, it a _l s his property at \$									

was updated in 1881 and 1887 and record the construction of a new tenant house and new bam. No mention is made of a new or improved dwelling, and since stylistically the house appears to pre-date 1887, it is inferred that it is the present house is that described in the 1876 assessment (5).

(continuation sheet)

Major Bibliographical References

Survey No. AA-1073

(1) 1798 Federal Direct Tax Records, Anne Arundel County, Maryland Hall of Records

(2) Chancery Court Records of Anne Arundel County, Book 159 Folio 644

(3) 1860 Martinett Atlas of Anne Arundel County

nne Arundel County Tax Assessments 1876-1893, District 5, p. 280, Maryland Hall of Records

DHCP/DHCD

410-514-7600

100 Community Place

Crownsville, MD 21032-2023

D			
B Zone	Easting	Northing	
D			
F			
H			
-	boundaries		
county	code		
county		code	
Survey	date Octob	er 1996	
·	telephone	(410) 222-7441	
	state	Maryland	
ure to be found	I in the Annotated	t.	
	for information an y infringement of	d	
	F H Sounded by Hotate or county county county county sentory was offiure to be found	F H H H H H H H H H H H H H H H H H H H	

Continuation Sheet

Survey No. AA-1073

7. 1 Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

n first inspection, Femglen Manor appears to display three building episodes; front block, rear ell, and one-story bathroom/screen porch addition. The entire front block appears to have been constructed at the same time, however, architectural evidence uncovered during recent stabilization projects suggest a more complicated building evolution.


When investigators visited the building, portions of the foundation and wall siding were temporarily removed from the west side of the main facade, revealing between the studs the presence of brick nogging According to the owners, nogging was not present on the east side of the facade. However, when exterior siding was removed from that section of the facade, unattached riven lath was found, located between the exterior siding and the 19th century interior plaster. Lying under the house in this area were several exceptionally large bricks. Measuring 9 1/2" x 4 1/4" x 3", these bricks appear handmade and are glazed with hughes mixed with pink, grey, and yellow.


Unfortunately much of the foundation is rebuilt and, due to termite damage, large sections of the sills are replaced. Enough of the dwellings substructure is exposed to raise questions, but regrettably too much original fabric is removed or unexposed to definitively answer them.

8.1 Prepare both a summary paragraph of significance and a general statement of history and support.

Charles Pumphrey died in 1897 and his estate was divided amongst his eleven heirs. Charles' son Herbert inherited "the homeplace and 60 acres". He later sold it to his brother Thales C. Pumphrey. In 1954 Lasting Homes purchased and subdivided the surrounding property. While Femglen Manor's integrity of association and location is compromised by modern development, it sits back from the road and is surrounded by mature trees. Its owners are in the process of repairing and restoring the house in 2-manner consistent with his character.

Fernglen Manor is significant as a typical example of a vemacular gothic-revival style I-house. Its styling and form are consistent with that associated with affluent nineteenth century farm families. Its importance is further enhanced due to its association with truck farming, which when Fernglen Manor was built, was the dominant economic activity of the region.







AA= 1073 FERNGLEN MANOR ANNE ARUNDEL CO., MARYLAND Photo By SHERRI M. MARSH, AUG 1996 NEG. AT MARYLAND SHAD Ling The Library 1 of 7



AA= 1073 FERNGLEN MANOR ANNE ARUNDEL CO., MARYLAND Photo BY SHERRI M. MARSH, AUG. 1996 NEG. AT MARYLAND SHPO Mark to the 2 Of 2